

Laser Safety Startup Directions

1. Lock lab doors when the laser is **ON**.



2. Communicate laser status often with other lab occupants.



3. Remove jewelry worn on arms and hands.




4. Cover reflective parts of clothes like buttons or zippers.



5. Wear the correct safety eyewear for laser(s) in use.



6. Check beam path & stops, focal points, and enclosures.



7. Activate warning lights before turning Class 4 laser **ON**.



Make sure to follow the Standard Operating Procedures (SOPs) for the laser and to work closely with your mentor to design a safe experiment.